Derry 056/084

Date of Inspection: 10/01/2007 FORDWAY ROAD

Date Report Sent: 12/5/2007 Over

Picture taken during inspection

BEAVER BROOK

Owner: Municipality

Recommended Postings:

Weight: E2 

✓ Weight Sign OK

Width: Not Required 

✓ Width Sign OK

Optional Centerline Height Sign Rec: None (Feet) Under: 0.00

Route:

**Condition:** Not on the Redlist **Structure Type and Materials:** 

Deck: N N/A (NBI)

Superstructure: N N/A (NBI)

Number of Spans Main Unit: 2

Number of Approach Spans: 0

Substructure: N N/A (NBI)

Main Span Material and Design Type

Culvert: 5 Fair

Aluminum or Iron Culvert

**Sufficiency Rating:** 63%

NBI Status: Structurally Deficient

Bridge Rail: Meets Standards NH Bridge Type: Metal Pipe

Rail Transition: Meets Standards

Deck Type: No Deck ( N/A - NBI)

Bridge Approach Rail: Meets Standards

Wearing Surface: No Deck ( N/A - NBI)

Approach Rail Ends: Substandard

Membrane: No Deck ( N/A - NBI)

Deck Protection: No Deck (N/A - NBI)

Pavement thickness: 3.0 in

Curb Reveal: Not Applicable

Bridge Dimensions: Plan Location: Unknown

Length Maximum Span: 17.0 ft Total Bridge Length: 38.0 ft

Left Curb/Sidewalk Width: 0.0 ft Right Curb/Sidewalk Width: 0.0 ft

Width Curb to Curb: 0.0 ft Total Bridge Width: 0.0 ft

Approach Roadway Width (W/ Shoulders): 26.0 ft Median: No median

Bridge Skew: 0.00 °

**Bridge Service:** 

Type of Service on Bridge: Highway Year Built: 1971

Type of Service under: Waterway Year Rebuilt: Not Rebuilt

Lanes on bridge: 2 Detour Length: 1.0 mi

Lanes Under: NA

AADT: 5900 Percent Trucks: 4% Year of AADT: 2005 Future AADT: 5476 Year of Future AADT: 2025

### Derry 056/084

# **Bridge Inspection Report**

Federal or State Definition Bridge: Fed. Definition Bridge

Roadway Functional Class: Urban Local

New Hampshire Highway System and Class: Compact Highway

Eligibility for the National Register of Historic Places: Not Eligible

Traffic Direction: Two-way traffic

### National Bridge Inventory (NBI) Appraisal Ratings:

Deck Geometry: Not Applicable (NBI)
Underclearances: Not Applicable (NBI)
Approach Alignment: Above Mininimum Criteria
Structural Evaluation: Intolerable, Replacement

Channel/Channel Protection: Bank Slumping

Waterway Adequacy: Equal Desirable Criteria Bridge Scour Critical Status: Stable for extreme flood

Riprap Condition: Fair Condition
Debris Present: Debris Present
Date of Underwater Inspection: Not Applicable

#### **AASHTO CoRe Element Condition State Data:**

No.	Description	Env.	Material Notes and Condition Notes
215	Reinforced Concrete Abutment	NORTH BAR INVERT AT I	AT EAST HEADWALL IS CRACKED, SPALLED AND SETTLED. EAST END OF RREL SETTLED FOUR TO FIVE INCHES FROM HEADWALL. NEW CONCRETE END OF NORTH BARREL. CONCRETE INVERT INSTALLED AT SOUTH LL LENGTH WITH INVERT.
217	Other Material Abutment	Moderate STONE MAS	SONRY AT WEST IS VOIDED AND SETTLED.
240	Culvert (includes Steel, Aluminum and Galvanized)	PIPE. COF	5' OF COVER. 9" X 2.5" X .150" ALUMINUM PLATE. S DISTORTED WITH SAGS IN ROOF. NEW CONCRETE INVERT AT SOUTH RROSION HOLES UP TO 1" DIAMETER. SEVERAL DENTS AND TEARS. RREL SETTLED AND KINKED AT NORTH SIDE. NEW CONCRETE AT NORTH RT.
360	Settlement Condition Warning Flag	Moderate	Element record added 2006-12-21.

No.	Description	Env.	Quantity	Units	State 1	State 2	State 3	State 4	State 5
215	Reinforced Concrete Abutment	Moderate	20	(LF)	0 %	0 %	100 %	0 %	
217	Other Material Abutment	Moderate	20	(LF)	0 %	0 %	100 %	0 %	
240	Culvert (includes Steel, Aluminum and C	Moderate	89	(LF)	0 %	0 %	100 %	0 %	
360	Settlement Condition Warning Flag	Moderate	1	(EA)	100 %	0 %	0 %		

Derry 056/084

**Bridge Notes:** 

REMOVED FROM RL 10/1/07

Approach and Roadway Notes: ASPHALT CRACKED. W-BEAM RAIL- DAMAGE AT NORTHEAST AND NORTHWEST.

ASPHALT ERODING INTO TRAVEL WAY, SOUTHEAST.

**Inspection History:** 

Inspection Date: 10/01/2007

Inspector: DPC

Deck: N N/A (NBI) Super: N N/A (NBI)

Notes:

DPC - inspection comments -

Substr: N N/A (NBI) Culvert: 5 Fair

CULVERT: MP'S-BOTH PIPES DISTORTED WITH SAGS IN ROOF. INVERT OF BOTH PIPES SETTLED AT DOWNSTREAM. CORROSION HOLES UP TO ONE INCH DIAMETER. SEVERAL DENTS. DAMAGED AREAS AT BOTH ENDS OF SOUTH BARREL. EAST END OF NORTH BARREL SETTLED FOUR TO FIVE INCHES FROM HEADWALL. NORTH SIDE TOP

OF BARREL SETTLED. CONCRETE INVERT INSTALLED IN SOUTH BARREL.

PIC(s): C359 - 2,3.

Inspection Date: 12/21/2006

Inspector: RLM

Deck: N N/A (NBI)

Notes:

RLM inspection comments -

Super: N N/A (NBI) Substr: N N/A (NBI) Culvert: 4 Poor

CULVERT: MP'S-BOTH PIPES DISTORTED WITH SAGS IN ROOF. INVERT OF BOTH PIPES SETTLED AT DOWNSTREAM. CORROSION HOLES UP TO ONE INCH DIAMETER. SEVERAL DENTS. DAMAGED AREAS AT BOTH ENDS OF SOUTH BARREL. EAST END OF NORTH BARREL SETTLED FOUR TO FIVE INCHES FROM HEADWALL. NORTH SIDE TOP OF BARREL SETTLED. CONCRETE INVERT INSTALLED IN SOUTH BARREL.

PIC: C332-28-32

Inspection Date: 08/15/2005 Notes:

Inspector: RLM

Deck: N N/A (NBI)

RLM inspection comments -

Super: N N/A (NBI) Substr: N N/A (NBI) Culvert: 4 Poor

CULVERT: MP'S-BOTH PIPES DISTORTED WITH SAGS IN ROOF. INVERT OF SOUTH PIPE SETTLED AT DOWNSTREAM. CORROSION HOLES UP TO ONE INCH DIAMETER. SEVERAL DENTS AND TEARS. BOTH UNDERMINED. NORTH BARREL SETTLED AND KINKED AT NORTH SIDE.

SOUTH BARREL. SOUTH INVERT PLATES HEAVED UP 4 TO 5 INCHES FOR 10 FOOT LENGTH; PLATES PULLED THROUGH BOLTS.

PIC(S): C298- 12- 18.

Inspection Date: 08/11/2003

Inspector: RLM

Deck: N N/A (NBI)

Notes:

Sufficiency Rating Calculation Accepted by DEP at 7/20/2004 14:25:48

Super: N N/A (NBI) Substr: N N/A (NBI)

Culvert: 5 Fair

RLM inspection comments -

CULVERT: MP'S-BOTH PIPES DISTORTED WITH SAGS IN ROOF. INVERT OF SOUTH PIPE SETTLED AT DOWNSTREAM. CORROSION HOLES UP TO ONE INCH DIAMETER. SEVERAL DENTS AND TEARS. BOTH UNDERMINED. NORTH BARREL SETTLED AND

KINKED AT NORTH SIDE.

PICTURES: C190-04 THRU 07.

Derry 056/084

Inspection History:		
Inspection Date: 01/23/2001  Notes: Sufficiency Rating Calculation Accepted by RLM inspection comments - CULVERT: MP's- Both pipes distorted wit downstream. Several corrosion holes exist dents and tears. Both undermined. NORT SIDE. Headwalls/Wingwalls- Concrete at West voided, settled. Asphalt aprons upst	th sags in roofs, invert of south pipe settled st and vary in size from 1/4 inch to 1 inch + TH BARREL SETTLED AND KINKED AT N East cracked, spalled, settled. Stone Mas	. Several IORTH
Notes: Sufficiency Rating Calculation Accepted by FNM inspection comments - MP's- Both pipes distorted with sags in roc corrosion holes exist and vary in size from undermined. Headwalls/Wingwalls- Concat West voided, settled. Asphalt aprons up	ofs, invert of south pipe settled downstream of 1/4 inch to 1 inch +. Several dents and te rete at East cracked, spalled, settled. Stol	ears. Both
Inspection Date: 02/01/1997 Notes: Sufficiency Rating Calculation Accepted by	Inspector: Not Available y DEP at 12-23-98 07:59:01	Deck: N N/A (NBI) Super: N N/A (NBI) Substr: N N/A (NBI) Culvert: 5 Fair
Inspection Date: 08/01/1995 Notes:	Inspector: Not Available	Deck: N N/A (NBI) Super: N N/A (NBI) Substr: N N/A (NBI) Culvert: 5 Fair
Inspection Date: 01/01/1994 Notes:	Inspector: Not Available	Deck: N N/A (NBI) Super: N N/A (NBI) Substr: N N/A (NBI) Culvert: 5 Fair
Inspection Date: 08/01/1991 Notes:	Inspector: Not Available	Deck: N N/A (NBI) Super: N N/A (NBI) Substr: N N/A (NBI) Culvert: N N/A (NBI)
Copy Distribution:  (2) Bureau of Municipal Hghways (3) Bureau of Municipal Hghways Bureau of Turnpikes	Border State Bureau of Rail and Transit Army Corps Of Engineers Railroad	Dept. of Res. and Econ. Dev. Dept. of Environmental Services USDA Forest Service Bureau of Traffic

Derry 056/088

# **Bridge Inspection Report**

Date of Inspection: 10/01/2007 FLORENCE STREET Date Report Sent: 10/18/2007 Over Picture taken during inspection SHIELDS BROOK Owner: Municipality ✓ Critical Deficiency Status Heavy section loss on steel stringers has reduced the safe Live Load capacity of this structure. See reduced recommended load posting below. **Recommended Postings:** Weight: 'Weight Limit 10 Tons' Weight Sign OK CURRENTLY POSTED "WEIGHT LIMIT 15 TONS or 70% OF LEGAL LOAD". New Signage Required for Reduced Posting. Width Sign OK Width: Not Required Clearances: Over: ✓ Height Signs OK Primary Height Sign Recommendation: None (Feet) Under: 0.00 Optional Centerline Height Sign Rec: None Route: **Structure Type and Materials: Condition:** Municipal Redlist Number of Spans Main Unit: 1 Deck: 5 Fair Number of Approach Spans: 0 Superstructure: 4 Poor Substructure: 6 Satisfactory Main Span Material and Design Type Culvert: N N/A (NBI) Steel Multiple Beam **Sufficiency Rating:** 20.8% **NBI Status:** Not Applicable Bridge Rail: Substandard NH Bridge Type: Jack Arch Rail Transition: Substandard Deck Type: Concrete, Cast in Place Bridge Approach Rail: Substandard Wearing Surface: Bituminous Membrane: None Approach Rail Ends: Substandard Deck Protection: None Pavement thickness: 3.0 in Curb Reveal: Not Applicable Plan Location: Unknown **Bridge Dimensions:** Length Maximum Span: 16.0 ft Total Bridge Length: 19.0 ft Left Curb/Sidewalk Width: 4.0 ft Right Curb/Sidewalk Width: 4.0 ft Width Curb to Curb: 19.3 ft Total Bridge Width: 27.9 ft Approach Roadway Width (W/ Shoulders): 18.0 ft Median: No median Bridge Skew: 30.00° **Bridge Service:** Type of Service on Bridge: Highway and Pedestrian Year Built: 1935 Type of Service under: Waterway Year Rebuilt: Not Rebuilt Lanes on bridge: 2 Detour Length: 1.0 mi Lanes Under:

Derry 056/088

NA

AADT: 200 Percent Trucks: 4% Year of AADT: 2003 Future AADT: 296 Year of Future AADT: 2025

Federal or State Definition Bridge: NH Definition Bridge

Roadway Functional Class: Urban Local

New Hampshire Highway System and Class: Compact Highway

Eligibility for the National Register of Historic Places: Not Eligible

Traffic Direction: Two-way traffic

#### National Bridge Inventory (NBI) Appraisal Ratings:

Deck Geometry: Intolerable, Correctable
Underclearances: Not Applicable (NBI)
Approach Alignment: Equal Desirable Criteria
Structural Evaluation: Intolerable, Replacement

Channel/Channel Protection: Bank Slumping

Waterway Adequacy: Equal Minimum Criteria
Bridge Scour Critical Status: Stable for extreme flood

Riprap Condition: Fair Condition
Debris Present: Debris Present
Date of Underwater Inspection: Not Applicable

#### **AASHTO CoRe Element Condition State Data:**

No.	Description	Env. Material Notes and Condition Notes
13	Concrete Deck - Unprotected, with Asphalt Pavement	Moderate  ASPHALT- CRACKED.
107	Painted Steel Beam or Girder (Open Web)	Moderate  MODERATE RUST AND SECTION LOSS. STRINGER #2,4,8 FLANGE HOLED AT EAST.  THIN AREAS. STRINGER #1,4,8 FLANGE HOLED AT WEST.
215	Reinforced Concrete Abutment	Moderate  MEDIUM CRACKS AT ABUTMENTS. MINOR SPALLS AT WINGS.
334	Coated Metal Bridge Railing	Severe ** Steel Channel Rail ** CHANNEL ON STEEL POST DAMAGED. POOR CONDITION.
359	Soffit of Conc Deck or Slab Condition Warning Flag	Moderate  FORMS HEAVILY RUSTED. SPALLS AT EXPOSED AREAS. HEAVY LEAKING. CURBS CRACKED AND SPALLED.
363	Section Loss Condition Warning Flag	Moderate Element record added 2007-10-01.

Derry 056/088

No.	Description	Env.	Quantity	Units	State 1	State 2	State 3	State 4	State 5
13	Concrete Deck - Unprotected, with Aspl	Moderate	527	(SF)	0 %	100 %	0 %	0 %	0 %
107	Painted Steel Beam or Girder (Open We	Moderate	190	(LF)	0 %	0 %	0 %	50 %	50 %
215	Reinforced Concrete Abutment	Moderate	75	(LF)	0 %	100 %	0 %	0 %	
334	Coated Metal Bridge Railing	Severe	39	(LF)	0 %	0 %	100 %	0 %	0 %
359	Soffit of Conc Deck or Slab Condition W	Moderate	1	(EA)	0 %	0 %	100 %	0 %	0 %
363	Section Loss Condition Warning Flag	Moderate	1	(EA)	100 %	0 %	0 %	0 %	

#### **Bridge Notes:**

Approach and Roadway Notes: ASPHALT - CRACKED AND SETTLED. CHANNEL RAIL DAMAGED.

#### **Inspection History:**

Inspection Date: 10/01/2007 Inspector: DPC Deck: 5 Fair

Notes: Super: 4 Poor

DPC inspection comments - Substr: 6 Satisfactory

DECK: ELEMENTS IN FAIR CONDITION. FORMS IN PLACE. Culvert: N N/A (NBI)

SUPERSTRUCTURE: ELEMENTS IN POOR CONDITION. STRINGERS HOLED AT LOWER

FLANGES.

SUBSTRUCTURE: ELEMENTS IN SATISFACTORY CONDITION.

Inspection Date: 12/21/2006Inspector: DPCDeck: 5 FairNotes:Super: 4 PoorDPC inspection comments -Substr: 6 SatisfactoryDECK: ELEMENTS IN FAIR CONDITION. FORMS IN PLACE.Culvert: N N/A (NBI)

SUPERSTRUCTURE: ELEMENTS IN POOR CONDITION. STRINGERS HOLED AT LOWER

FLANGES.

SUBSTRUCTURE: ELEMENTS IN SATISFACTORY CONDITION.

Inspection Date: 08/15/2005 Inspector: RLM Deck: 5 Fair

Notes: Super: 5 Fair

RLM inspection comments - Substr: 6 Satisfactory

DECK: ELEMENTS IN FAIR CONDITION. FORMS IN PLACE. Culvert: N N/A (NBI)

SUPERSTRUCTURE: ELEMENTS IN FAIR CONDITION. SUBSTRUCTURE: ELEMENTS IN SATISFACTORY CONDITION.

Inspection Date: 10/05/2004 Inspector: DPC Deck: 5 Fair Notes: Super: 5 Fair

Sufficiency Rating Calculation Accepted by DEP at 06/07/2005 10:36:02

DPC inspection comments - Substr: 6 Satisfactory

Culvert: N N/A (NBI)

DECK: ELEMENTS IN FAIR CONDITION. FORMS IN PLACE. SUPERSTRUCTURE: ELEMENTS IN FAIR CONDITION. SUBSTRUCTURE: ELEMENTS IN SATISFACTORY CONDITION.

Inspection Date: 08/11/2003Inspector: DPCDeck: 5 FairNotes:Super: 5 Fair

Sufficiency Rating Calculation Accepted by DEP at 7/20/2004 14:25:48

DPC inspection comments - Substr: 6 Satisfactory

Culvert: N N/A (NBI)

DECK: ELEMENTS IN FAIR CONDITION. FORMS IN PLACE. SUPERSTRUCTURE: ELEMENTS IN FAIR CONDITION. SUBSTRUCTURE: ELEMENTS IN SATISFACTORY CONDITION.

Derry 056/088

<u>Ins</u>	pection	<u> History:</u>

Inspection Date: 01/07/2002	Inspector: RLM	Deck: 5 Fair
Notes:		Super: 5 Fair
Sufficiency Rating Calculation Accepted I	by DEP at 06-06-2002 09:24:55	Substr: 6 Satisfactory

Culvert: N N/A (NBI) RLM inspection comments -

DECK: ELEMENTS IN FAIR CONDITION.

SUPERSTRUCTURE: ELEMENTS IN FAIR CONDITION.

SUBSTRUCTURE: ELEMENTS IN SATISFACTORY CONDITION.

Deck: 5 Fair Inspection Date: 01/29/2001 Inspector: DPC Super: 5 Fair Notes:

Substr: 6 Satisfactory Sufficiency Rating Calculation Accepted by DEP at 07-20-2001 15:59:31 DPC inspection comments -Culvert: N N/A (NBI)

DECK- ELEMENTS IN FAIR CONDITION.

SUPERSTRUCTURE- ELEMENTS IN FAIR CONDITION.

SUBSTRUCTURE- ELEMENTS IN SATISFACTORY CONDITION.

Deck: 5 Fair Inspection Date: 02/09/2000 Inspector: DPC Super: 5 Fair Notes:

Sufficiency Rating Calculation Accepted by DEP at 10-03-2000 13:08:30 Substr: 6 Satisfactory DPC inspection comments -Culvert: N N/A (NBI)

Channel rail damaged.

Deck: Asphalt - cracked, settled. Concrete - moderate leaking, minor spalls, galvanized

forms heavily rusted and holed. Pipe dr

Deck: 6 Satisfactory Inspection Date: 01/15/1999 Inspector: FNM Notes: Super: 5 Fair Sufficiency Rating Calculation Accepted by DEP at 03-09-1999 15:19:27 Substr: 6 Satisfactory FNM inspection comments -Culvert: N N/A (NBI)

Channel rail damaged.

Deck: Asphalt- cracked, settled. Concrete- moderate leaking, minor spalls, galvanized forms

heavily rusted and holed. Pipe drain

Inspection Date: 01/01/1998 **Inspector:** Not Available Deck: 6 Satisfactory Notes: Super: 5 Fair Substr: 7 Good Sufficiency Rating Calculation Accepted by DEP at 12-23-98 07:59:01 Culvert: N N/A (NBI)

Inspection Date: 01/01/1997 **Inspector:** Not Available **Deck:** 6 Satisfactory

Super: 6 Satisfactory Notes: Substr: 7 Good Culvert: N N/A (NBI)

Inspection Date: 01/01/1996 Deck: 7 Good **Inspector:** Not Available Super: 6 Satisfactory Notes:

Substr: 7 Good Culvert: N N/A (NBI)

Inspection Date: 01/01/1994 **Inspector:** Not Available Deck: 7 Good Notes: Super: 7 Good

Substr: 7 Good Culvert: N N/A (NBI)

Derry 056/088

Inspection History:		
Inspection Date: 08/01/1991 Notes:	Inspector: Not Available	Deck: 7 Good Super: 7 Good Substr: 7 Good Culvert: N N/A (NBI)
Copy Distribution:  (2) Bureau of Municipal Hghways (3) Bureau of Municipal Hghways Bureau of Turnpikes	Border State Bureau of Rail and Transit Army Corps Of Engineers Railroad	Dept. of Res. and Econ. Dev. Dept. of Environmental Services USDA Forest Service Bureau of Traffic

Derry 066/092

Date of Inspection:10/02/2007SOUTH AVENUEDate Report Sent:12/5/2007Over

✓ Picture taken during inspection SHIELDS BROOK

Owner: Municipality

Recommended Postings:

Weight: E2 

✓ Weight Sign OK

Width: Not Required 

✓ Width Sign OK

Primary Height Sign Recommendation: None Clearances: Over: ✓ Height Signs OK

Optional Centerline Height Sign Rec: None (Feet) Under: 0.00

Route:

**Condition:** Not on the Redlist **Structure Type and Materials:** 

Deck: 5 Fair Number of Spans Main Unit: 1
Superstructure: 5 Fair Number of Approach Spans: 0

Substructure: 6 Satisfactory

Main Span Material and Design Type

Culvert: N N/A (NBI)

Steel Multiple Beam

Sufficiency Rating: 58.3%

NBI Status: Not Applicable

Bridge Rail: Substandard NH Bridge Type: Jack Arch

Rail Transition: Substandard Deck Type: Concrete, Cast in Place

Bridge Approach Rail: Substandard Wearing Surface: Bituminous Approach Rail Ends: Substandard Membrane: None Deck Protection: None

Pavement thickness: 3.0 in

Curb Reveal: Not Applicable

Plan Location: Unknown

Length Maximum Span: 18.0 ft Total Bridge Length: 20.0 ft
Left Curb/Sidewalk Width: 5.0 ft
Width Curb to Curb: 26.1 ft Total Bridge Width: 36.7 ft
Approach Roadway Width (W/ Shoulders): 22.0 ft Median: No median

Bridge Skew: 15.00 °

**Bridge Service:** 

Type of Service on Bridge: Highway and Pedestrian Year Built: 1935

Type of Service under: Waterway Year Rebuilt: Not Rebuilt

Lanes on bridge: 2 Detour Length: 1.0 mi

Lanes Under: NA

AADT: 3500 Percent Trucks: 4% Year of AADT: 2003 Future AADT: 5624 Year of Future AADT: 2025

Federal or State Definition Bridge: NH Definition Bridge

Roadway Functional Class: Urban Local

New Hampshire Highway System and Class: Compact Highway

Eligibility for the National Register of Historic Places: Not Eligible

Traffic Direction: Two-way traffic

#### National Bridge Inventory (NBI) Appraisal Ratings:

Deck Geometry: Intolerable, Correctable
Underclearances: Not Applicable (NBI)
Approach Alignment: Equal Desirable Criteria
Structural Evaluation: Above Min. Tolerable

Channel/Channel Protection: Minor Damage

Waterway Adequacy: Equal Desirable Criteria Bridge Scour Critical Status: Stable for extreme flood

Riprap Condition: Fair Condition

Debris Present: Debris Present

Date of Underwater Inspection: Not Applicable

#### **AASHTO CoRe Element Condition State Data:**

No.	Description	Env.	Material Notes and Condition Notes
13	Concrete Deck -	Moderate	** Jack Arch ** STEEL FORMS IN PLACE. CONCRETE NOT VISIBLE.
	Unprotected, with Asphalt Pavement	FORMS HEA	AVILY RUSTED.
107	Painted Steel Beam or	Moderate	
	Girder (Open Web)		RUST AND SCALE ON CHANNELS HEAVY RUST AND PITTING ON CENTER BOTTOM FLANGE RUSTED TO KNIFE EDGE. PAINT POOR. BRACING
		STRAP RUS	TED OFF AT UPSTREAM.
215	Reinforced Concrete	Moderate	
	Abutment	LARGE VER	TICAL CRACK, LIGHT SPALLS.
334	Coated Metal Bridge	Moderate	
	Railing	RUST AT BA	SE.
359	Soffit of Conc Deck or	Moderate	
	Slab Condition Warning Flag	STEEL FOR	MS RUSTED, HOLED.

No.	Description	Env.	Quantity	Units	State 1	State 2	State 3	State 4	State 5
13	Concrete Deck - Unprotected, with Aspl	Moderate	732	(SF)	0 %	100 %	0 %	0 %	0 %
107	Painted Steel Beam or Girder (Open We	Moderate	299	(LF)	0 %	0 %	54 %	46 %	0 %
215	Reinforced Concrete Abutment	Moderate	98	(LF)	0 %	98 %	2 %	0 %	
334	Coated Metal Bridge Railing	Moderate	39	(LF)	99 %	1 %	0 %	0 %	0 %
359	Soffit of Conc Deck or Slab Condition W	Moderate	1	(EA)	0 %	100 %	0 %	0 %	0 %

Derry 066/092

Culvert: N N/A (NBI)

**Bridge Notes:** 

Approach and Roadway Notes: ASPHALT- OK.

**Inspection History:** 

Inspection Date: 10/02/2007 Inspector: RLM Deck: 5 Fair Notes: Super: 5 Fair

RLM inspection comments - Substr: 6 Satisfactory
DECK: STEEL FORMS RUSTED, HOLED.
Culvert: N N/A (NBI)

SUPERSTRUCTURE: BEAMS HEAVILY RUSTED WITH SECTION LOSS. SOUTHWEST

EXTERIOR HOLED.

SUBSTRUCTURE: CRACKS, SPALLS.

PIC(S): C359-5,6,7.

Inspection Date: 08/18/2005 Inspector: DPC Deck: 5 Fair Notes: Super: 5 Fair

DPC inspection comments - Substr: 6 Satisfactory
DECK: STEEL FORMS RUSTED, HOLED. Culvert: N N/A (NBI)

SUPERSTRUCTURE: BEAMS HEAVILY RUSTED WITH SECTION LOSS. SOUTHWEST

EXTERIOR HOLED.

SUBSTRUCTURE: CRACKS, SPALLS.

PIC(S): C190-08 THRU 12.

PIC: C298-35

Inspection Date: 08/11/2003 Inspector: RLM Deck: 5 Fair
Notes: Super: 5 Fair

Sufficiency Rating Calculation Accepted by DEP at 7/20/2004 14:25:48

Substr: 6 Satisfactory RLM inspection comments - Culvert: N N/A (NBI)

DECK: STEEL FORMS RUSTED, HOLED.

SUPERSTRUCTURE: BEAMS HEAVILY RUSTED WITH SECTION LOSS. SOUTHWEST

EXTERIOR HOLED.

SUBSTRUCTURE: CRACKS, SPALLS.

PICTURES: C190-08 THRU 12.

Inspection Date: 01/29/2001 Inspector: RLM Deck: 5 Fair

Notes: Super: 5 Fair

Sufficiency Rating Calculation Accepted by DEP at 07-20-2001 15:59:31

Substr: 6 Satisfactory

RLM inspection comments - DECK: Concrete not visible. Steel forms heavily rusted with section loss. Few holes.

Concrete curbs. Sidewalk- concrete at south has minor spalls. Paved at north. Drain pipes broken. Deck ends and joints leaking.

SUPERSTRUCTURE: I-beams- heavily rusted with section loss. Southwest exterior holed. Steel bracing bars rusted and holed.

SUBSTRUCTURE: Concrete abutments- large cracks, light spalls. Backwalls- stone loose with voids. Bridgeseat- concrete- medium cracks, light spalls. Wings- concrete- minor spalls.

Footings- concrete toe wall- light cracks and spalls.

Channel- light erosion and drift.

Derry 066/092

Inspection History:		
curbs. Sidewalk- concrete at south with r Deck ends and joints leaking. Super: I-beams- heavily rusted with sect Sub: Concrete abutments- large cracks,	neavily rusted with section loss. Few holes. Cominor spalls. Paved at north. Drain pipes brown ion loss. Bracing-steel bars-rusted. Iight spalls. Backwalls-stone loose with void the spalls. Wings-concrete-minor spalls. Fo	ken. Is.
Inspection Date: 02/01/1997 Notes: Sufficiency Rating Calculation Accepted by	Inspector: Not Available by DEP at 12-23-98 07:59:03	Deck: 6 Satisfactory Super: 5 Fair Substr: 6 Satisfactory Culvert: N N/A (NBI)
Inspection Date: 08/01/1995 Notes:	Inspector: Not Available	Deck: 6 Satisfactory Super: 5 Fair Substr: 6 Satisfactory Culvert: N N/A (NBI)
Inspection Date: 01/01/1994 Notes:	Inspector: Not Available	Deck: 6 Satisfactory Super: 5 Fair Substr: 6 Satisfactory Culvert: N N/A (NBI)
Inspection Date: 08/01/1991 Notes:	Inspector: Not Available	Deck: 6 Satisfactory Super: 5 Fair Substr: 6 Satisfactory Culvert: N N/A (NBI)
Copy Distribution:  (2) Bureau of Municipal Hghways (3) Bureau of Municipal Hghways Bureau of Turnpikes	Border State Bureau of Rail and Transit Army Corps Of Engineers Railroad	Dept. of Res. and Econ. Dev. Dept. of Environmental Services USDA Forest Service Bureau of Traffic